
PN 301302

IGNITION ADAPTER - GM HEI (SMALL CAP/EXTERNAL COIL)


TO "CAM/HALL EFFECT" CONNECTOR ON XFI MAIN HARNESS



LARGE CAP HEI'S USE PINOUT SHOWN IN DASHED CONN. REQUIRES A DIFFERENT 4-WAY DISTRIBUTOR CONNECTOR. MUST ALSO SUPPLY POWER TO "BATT" TERMINAL ON CAP.


PN 301304

IGNITION ADAPTER - GM LT1 (LONG CONN. OPTISPARK)



ADDITIONAL HEI WIRING (FOR REFERENCE)

* FACTORY COIL / COIL DRIVER * (USE FACTORY WIRING OR FAST PN 9900100)




(2-WAY)+12V SWITCHED COIL/DIST PWR COIL DWELL SIGNAL WHITE "POINTS" INPUT ON AFTERMARKET IGNITION

(WIRE IGNITION TO COIL PER IGNITION'S INSTRUCTIONS.)

ADDITIONAL OPTISPARK WIRING (FOR REFERENCE)

B EST C GND


D + COIL DWELL SIGNAL



* AFTERMARKET IGNITION *

TO USE AFTERMARKET IGNITION, CONNECT WHITE "POINTS" WIRE (ECU PIN A11) FROM XFI MAIN HARNESS TO "POINTS" INPUT ON IGNTION.

WIRE IGNITION TO COIL PER IGNITION'S INSTRUCTIONS.



(0)

DENOTES SPLICE